

## Your Club - Hurricane Wilma

### Turf Grass Repair - Tree Hole Repair

Hole	Location South	Location North	Location East
1	3,800 sf	1,275 sf	3,325 sf
2	3,775 sf	5,180 sf	2,750 sf
3	1,970 sf	5,200 sf	3,850 sf
4	9,850 sf (fense)	27,700 sf	8,000 sf (fense)
5	2,700 sf		14,900 sf
6	1,500 sf	3,500 sf	2,150 sf
7	10,000 sf	2,900 sf	2,200 sf
8		5,125 sf	1,000 sf
9	1,200 sf	5,300 sf	22,000 sf (Bahia)
<b>Total</b>	<b>34,795 sf</b>	<b>56,180 sf</b>	<b>60,175 sf</b>

**Total Turf Repair** **151,150 sf**

#### Calculation for Repair

Preparation = removal, add soil and level      \$.90 / sf      \$136,035

**Total Cost of Turf Grass Repair - Tree Holes** **\$136,035**

